

0018

Internal OK
C/p 10/15/0032

From: Priscilla Burton
To: PAMGRUBAUGHLITTIG@utah.gov, MARYANNWRIGHT@utah.gov, KARLHOUSKEE
PER@utah.go...
Date: 10/11/2007 9:48 PM
Subject: update Crandall drill holes

I was at the Crandall drill sites today. Kerry Zewlinski (SITLA) was also there. The crane and cement and water are at the site, but mechanical problems with the crane truck delayed plugging of the hole at site 5. An hydraulic hose is being brought down from SLC and the contractors will be at the site again tomorrow (friday) at 7 am. I will also be at the site tomorrow until hole #5 is filled. Then work will progress to sites 3 and 4 (federal coal) through the weekend. Kerry and I determined that the brass identification cap must be placed between 3 - 7 feet below the existing surface on several pads, in order that the plug be at or just below grade when the pad is reclaimed. We will try to use micro-relief to expose the brass ID tag, but wonder whether having the brass ID on the surface is an issue for the BLM or UEI? My cell phone is 435-609-1015 (last digit changed from before) and Kerry can be reached at 801-643-3061. There is cell service at the saddle of East Mountain.

Priscilla Burton
Certified Professional Soil Scientist
Utah Division of Oil Gas & Mining
Price Field Office
455 West Rail Road Ave.
Price UT 84501

priscillaburton@utah.gov
(435) 613-1146 x 207