



OGMCOAL DNR <ogmcoal@utah.gov>

00150032 Crandall Canyon Burma Pond Inspection

1 message

Priscilla Burton <priscillaburton@utah.gov>

Thu, Jan 24, 2013 at 2:54 PM

To: jmarshall@coalsource.com, OGMCOAL DNR <ogmcoal@utah.gov>, Ken Hoffman <kenhoffman@utah.gov>, seopllc@emerytelcom.net

Hi Jay,

After we talked on the phone, I learned that Dan Guy's Sedimentation and Drainage Plan (Attach 7) describes UD-1 as greater than or equal to 15 in. deep and with 1h:1v sideslopes. So, I asked Jerry Criepps to finish the ditch to those specifications. Before getting started, he was going to discuss the best way to accomplish this with you. An image of the ditch is attached.

Priscilla Burton

[435-613-3733](tel:435-613-3733)PriscillaBurton@utah.gov

Sr. Environmental Scientist
Coal Program/Price Field Office
Utah Division of Oil, Gas & Mining
319 Carbonville Road, Ste. C
Price UT 84501

**IMGP0017.JPG**

1753K

