



REG-4-87

file

John R. Sca

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 2-13-87
10:30-12:00

Permittee and/or Operators Name: Southern Utah Fuel Company
Business Address: P.O. Box P Salina, Ut. 84654
Mine Name: Convulsion Cyn Permit Number: ACT/041/002
Type of Mining Activity: Underground Surface Other
County: Sevier
Company Official (s): Mike Davis
State Official(s): Holland Shepherd
Partial: Complete: Date of Last Inspection: 1-8-87
Weather Conditions: cloudy and cold, drizzle mixed snow, slight runoff
Acreage: Permitted 6194 Disturbed 27.8 Regraded 0 Seeded 0 Bonded 27.8
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION 2-13-87

(Comments are Numbered to Correspond with Topics Listed Above)

4.b. Diversions:

The operators diversion ditches and inlets in East Spring and Mud Spring Canyons appeared well maintained and operational.

4.c. Sediment Pond:

The operator's sediment pond was not discharging at this time. The pond's level was approximately 3-4 feet below the discharge point.

4.d. Other Sediment Controls:

All sediment controls were intact and functioning well. I detected no problems and have no further recommendations at this time.

Copy of this Report:

Mailed to: Mike Davis, Donna Griffin
Given to: Joe Helfrich, Susan Linner

Inspectors Signature and Number: Holland Shepherd Date: 2-18-87