

0007



**Southern Utah Fuel Company**

a subsidiary of The Coastal Corporation

P.O. Box P • Salina, Utah 84654 • (801) 529-7428

Mine: (801) 637-4880

*Dieg Mue file  
Route thru  
+ Boston  
S. Quinn*

**RECEIVED**  
MAY 25 1989

DIVISION OF  
OIL, GAS & MINING

May 22, 1989

Dr. Dianne R. Nielson  
Division of Oil, Gas & Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Dear Dr. Nielsen:

For your information, please find enclosed a copy of Southern Utah Fuel Company's quarterly sediment pond inspection reports conducted May 10, 1989.

Sincerely,  
SOUTHERN UTAH FUEL COMPANY

*Mike Davis*

Mike Davis  
construction Engineer

MD/jm

Enclosure

SOUTHERN UTAH FUEL COMPANY

Minesite Sediment Pond Quarterly Inspection Report

Inspector Mike Davis Date May 10, 89

1. Dam Structural Weakness

A. Cracks or scarps on crest None Observed

B. Cracks or scarps on slope None Observed

C. Sloughing or bulging on slope None Observed

2. Major Erosion Problems None Observed

3. Surface Movements of Surrounding Slopes None Observed

4. Visible Sumps or Sinkholes in Slurry Surface None Observed

5. Clogging

A. Spillway channels and pipes None Observed

B. Decant system None Observed - System closed

C. Diversion ditches None observed

6. Seepage (Specify Location, Color and Approximate Volume) \_\_\_\_\_

*None Observed*

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

7. Other Comments \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_