



11-87  
0007

*File*

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: 6/11/87  
11:15 am to 1:00 pm

Permittee and/or Operators Name: Summit Minerals, Inc.  
Business Address: 221 West 2100 South, Salt Lake City, Utah 84115  
Mine Name: Summit Minerals #1 Permit Number: INA/043/001  
Type of Mining Activity: Underground  Surface  Other   
County: Summit  
Company Official (s): Barbara Filas  
State Official(s): Randy Harden  
Partial:  Complete:  Date of Last Inspection: 4/16/87  
Weather Conditions: Clear and Warm 75 Degrees  
Acreage: Permitted 0 Disturbed 16 Regraded  Seeded  Bonded 16  
Enforcement Action: None.

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( X )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( X )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( X )	( )
7. COAL PROCESSING WASTE	( )	( )	( X )	( )
8. NONCOAL WASTE	( X )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( X )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( X )	( )
12. BACKFILLING AND GRADING	( )	( )	( X )	( )
13. REVEGETATION	( )	( )	( X )	( )
14. SUBSIDENCE CONTROL	( )	( )	( X )	( )
15. CESSATION OF OPERATIONS	( )	( )	( X )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( X )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( X )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION 6/11/87

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The operator is in compliance with the Board of Oil, Gas and Mining, order dated December 1985 and is proceeding with permitting of the reclamation plan. The Division is currently in the process of formulating the Findings Document and the Technical Analysis for permit approval.

4. HYDROLOGIC BALANCE:

b. DIVERSIONS

The main undisturbed area diversion ditch on the south end of the site which diverts runoff from the hillside above the portal area was found to have some erosion of the uphill embankment into the channel during the previous inspection. The operator has installed straw bales at the outlet of the diversion ditch as requested previously.

c. SEDIMENT PONDS AND IMPOUNDMENTS

The operator has maintained the inlet structures and sediment ponds in satisfactory condition. Previous repairs and maintenance to the structures has prevented further deterioration or need for additional work on the sediment pond or inlet.


d. OTHER SEDIMENT CONTROL MEASURES

Mr. Lyle Boyer was on the site at the time of the inspection. Mr. Boyer is one of the adjacent landowners and has easement for access to his property across the permit area. Mr. Boyer had employed a dozer to repair the out-take ditch from Chalk Creek. In accessing the site, the dozer forded the stream just above the bridge. Due to the steep outslope of the road embankment on the south side of the stream the dozer had to partially cut down and eliminate the berm along the road. Prior to arriving on site, the operator had commenced repairs on the berm and had placed straw bales along the area disturbed by the dozer. Complete repairs to the areas disturbed by the dozer had been affected prior to completion of the inspection.

Copy of this Report:

Mailed to: Donna Griffith - OSM Barbara Filas - Summit Mineral, Inc.

Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: #13  Date: 7/1/87