

0001

Document Information Form

Mine Number: C/043/008

File Name: Internal

To: DOGM

From:

Person N/A

Company SUMMIT COAL COMPANY

Date Sent: N/A

Explanation:

INSPECTION Report

cc:

File in: C/043/008, 1987, Internal

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

03-28-87

File

SA

INSPECTION REPORT

INSPECTION DATE & TIME: Dec. 18, 1987
1:30 p.m. to 4:00 pm

Permittee and/or Operators Name: Summit Coal Co.
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: ACT/043/002
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): Jack Blonquist
State Official(s): Rick Summers
Partial: Complete: Date of Last Inspection: 11/20/87
Weather Conditions: Clear, cold
Acreage: Permitted 129 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

03-28-87

File

SA

INSPECTION REPORT

INSPECTION DATE & TIME: Dec. 18, 1987
1:30 p.m. to 4:00 pm

Permittee and/or Operators Name: Summit Coal Co.
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: ACT/043/002
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): Jack Blonquist
State Official(s): Rick Summers
Partial: Complete: Date of Last Inspection: 11/20/87
Weather Conditions: Clear, cold
Acreage: Permitted 129 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES	()	()	()	()
UTILITY INSTALLATIONS	()	()	()	()

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No. 0001 Date NA
In CD/043/008, 1987, Internal
For additional information

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/002

DATE OF INSPECTION 12/18/87

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The operator received verbal approval on 12/15/87 to submit the stipulation response package to the Division on 12/18/87. A phone call to Mr. Dan Guy from the minesite confirmed that he was going to submit the package to the Price Field Office on 12/18/87 (that afternoon).

4. HYDROLOGIC BALANCE: b. DIVERSIONS

At the time of the November inspection, the operator was requested to install several bales in between the existing bales in UD-1 in order to shorten the flow path length and minimize erosion in the channel. The operator had installed the bales at the time of this inspection.

d. OTHER SEDIMENT CONTROL MEASURES

During the November inspection it was noted that although the catch basin located at the discharge from the access (exit) road diversion was working efficiently, the grouted riprap in the basin had settled and cracked. At the time of this inspection, the operator had personel working on the basin. The operator stated the basin would be repaired in the next two (working) days as weather conditions allowed.

16. ROADS b. DRAINAGE

All the inlets to the culverts were inspected. They were found to be well maintained and free of debris except for the culvert draining the county road beneath the access (exit) road. This culvert was partially blocked due to acculmulated sediments. The operator committed to cleaning the entrance of the culvert prior to next months inspection.

Copy of this Report:

Mailed to: Jack Blonquist, John Kathman (OSM)

Given to: NOV File, Sue Linner, Joe Helfrich

Inspectors Signature and Number: R. Summers #15 Date: 12/23/87