



0002

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

043/002 25

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Nov. 20, 1987
10:30 a.m. to 1:00 pm

Permittee and/or Operators Name: Summit Coal Co.
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: ACT/043/002
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): Jack Blonquist
State Official(s): Rick Summers
Partial: Complete: Date of Last Inspection: 10/29/87
Weather Conditions: Clear, cold
Acreage: Permitted 129 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	(X)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	(X)
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/002

DATE OF INSPECTION October 29, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The operator has requested an extension for submittal of response to stipulations 817.71-1-JRH and UMC 800-(1)-JRH. Approval was granted to submit this information with the remainder of the stipulation responses which are due 12-15-87.

4. HYDROLOGIC BALANCE: b. DIVERSIONS

The diversion UD-1 is currently functional. The operator has installed straw bales in the channel. These bales are in good condition and are functional. However, the operator was requested to install several bales in between the existing bales in order to shorten the flow path length and minimize erosion in the channel. The operator committed to installation of the bales within two weeks.

d. OTHER SEDIMENT CONTROL MEASURES

The catch basin located at the discharge from the access (exit) road diversion is working efficiently. Fine sediments had accumulated in the basin since the last inspection. The grouted riprap in the basin had settled and cracked, creating the potential for undermining the structure. The operator committed to repairing the basin within two weeks.

f. EFFLUENT LIMITATIONS

The sediment pond contained a small amount of runoff. There have been no discharges from the permit area since the last inspection.

16. ROADS c. SURFACING

The operator had intended to have the access (exit) road paved this fall. However, crews in the area were unable to initiate the job as scheduled. The operator informed me that the paving would be completed next spring.

Copy of this Report:

Mailed to: Jack Blonquist, John Kathman (OSM)

Given to: NOV File, Sue Linner, Joe Helfrich

Inspectors Signature and Number: R. Summers #15 Date: 12/2/87