

0003

9-28-88



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John
SU

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Sept. 19, 1988
11a.m. to 4p.m.

Permittee and/or Operators Name: Summit Minerals, Inc.
Business Address: 221 West 2100 South, Salt Lake City, Utah 84115
Mine Name: Summit Minerals #1 Permit Number: INA/043/001 7130
Type of Mining Activity: Underground XXX Surface ___ Other ___
County: Summit
Company Official (s): None
State Official(s): Harold G. Sandbeck and Rick Summers
Partial: ___ Complete: XXX Date of Last Inspection: June 17, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 0 Disturbed 16 Regraded ___ Seeded ___ Bonded 16
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1 PERMITS	()	(XX)	()	(XX)
2 SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	()	()	(XX)	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(XX)	()
b. DIVERSIONS	(XX)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	(XX)
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	()
f. EFFLUENT LIMITATIONS	(XX)	()	()	()
5. EXPLOSIVES	()	()	(XX)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(XX)	()
7. COAL PROCESSING WASTE	()	()	(XX)	()
8. NONCOAL WASTE	(XX)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(XX)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(XX)	()
12. BACKFILLING AND GRADING	()	()	(XX)	()
13. REVEGETATION	()	()	(XX)	()
14. SUBSIDENCE CONTROL	()	()	(XX)	()
15. CESSATION OF OPERATIONS	()	()	(XX)	()
16. ROADS				
a. CONSTRUCTION	()	()	(XX)	()
b. DRAINAGE CONTROLS	(XX)	()	()	()
c. SURFACING	(XX)	()	()	()
d. MAINTENANCE	(XX)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(XX)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(XX)	()	()	(XX)

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION Sept. 19, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments.

The operator was not available to accompany the undersigned inspector on this complete inspection. Rick Summers (Division Hydrologist) was present during the inspection to determine site stability. Mr. Summers stated that the mine site, including the highwall, appears to have remained stable over the last two years.

No evidence of mining or related activities were noted on the site. The impoundments contained no water and were not discharging. Ditches and diversions on the site appeared to be intact and operational. No potential hazards were found relating to sediment and erosion control for the site.

1. Permits. Summits Minerals has been denied a permit. Forfeiture of the reclamation bond is currently ongoing and the reader is referred to the Division correspondence files for additional information.

4. Hydrologic Balance:

d. Other Sediment Control Measures. Minor preventive maintenance is required on some strawbales and berms. Also, treatment is required along the northeast embankment of the gravel fill area. Since the controls are still effective and the gravel fill area appears stable (due to revegetation), a violation is not warranted.

18. Support Facilities/Utility Installations. The mine site bridge appears unstable to vehicular traffic but vehicular access to the mine site is restricted. On September 21, 1988, the undersigned inspector spoke to Tom Boyer (the surface owner) about access to the mine site. The main entrance gate is locked and access into the property through the back way is restricted by a number of locked gates.

Copy of this Report:

Mailed to: Jack Higgins (Summit Minerals), Price Office & Brian Smith (OSM)
Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: Harold D. Sanchez #27 Date: 9/21/88