



**INSPECTION REPORT**  
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/043/008

DATE OF INSPECTION 11/15/88

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. A partial inspection was conducted without Jack Blonquist. Jack Blonquist (Mine Manager) and Bill Blonquist (Partner) attended the closeout meeting. The mine is temporarily shut down.

1. Permits. On November 1, 1988, Division Personnel, Joe Helfrich and Harold G. Sandbeck, met with Jack Blonquist (Mine Manager) at the mine site. Mr. Blonquist was informed of the Division's procedure for handling patterns of violations. We discussed the current outstanding violations and identified the potential compliance issues which are unique to the Boyer Mine. At this time a potential exists for a pattern of violations to occur.

4. Hydrologic Balance:

b. Diversions.

N88-27-6-3, 1 of 3 was issued on October 17, 1988 for failure to finish the UD-1 culvert installation as required per the field amendment ACT/043/008-88E. The operator had until November 15, 1988 to complete the culvert installation to the county road right of way (approximately 40 additional feet plus the installation of the energy dissipater). During the inspection, the operator requested additional time to complete the culvert installation. The abatement date of N88-27-6-3, 1 of 3 is extended to November 30, 1988.

6. Disposal of Development Waste and Spoil.

N88-27-5-1

N88-27-5-1 was issued on September 23, 1988 for failure to abide by permit conditions for temporary storage of underground waste. The operator requested additional time via phone conversation on November 3, 1988. The operator stated that Utelite Corporation is currently upgrading their facility to handle additional waste material. The abatement date of N88-27-5-1 is extended to December 23, 1988.

The operator was informed that no additional extensions for N88-27-5-1 is possible and that the waste material must be removed from the mine site on or before December 23, 1988. Furthermore, it is the undersigned inspector's opinion that Utelite Corporation cannot handle all the waste material that the mine produces. Therefore, the operator was informed to research the potential for permitting a waste disposal site.

INSPECTION REPORT  
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/043/008

DATE OF INSPECTION 11/15/88

(Comments are Numbered to Correspond with Topics Listed Above)


15. Cessation of Operations. On October 13, 1988, the operator requested a temporary cessation of operations. On October 24, 1988, the Division informed the operator to abide by the requirements of UMC 817.131. During the inspection, the undersigned inspector received the operator's letter addressing the requirements of UMC 817.131.

Copy of this Report:

Mailed to: Jack Blonquist (Manager), Price Office and Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number:



#27 Date: 11/23/88