



0045

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

goh

Norman H. Bangarter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Feb. 15, 1988
9:30 a.m. to 12:30 p.m.

Permittee and/or Operators Name: Summit Coal Co.
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: ACT/043/008
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): Jack Blonquist
State Official(s): Rick Summers
Partial: Complete: Date of Last Inspection: 1/14/87
Weather Conditions: clear
Acreage: Permitted 170 Disturbed 5.5 Regraded Seeded Bonded 5.5
Enforcement Action: N88-15-1-1 was issued at the site.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/008

DATE OF INSPECTION 2/15/88

(Comments are Numbered to Correspond with Topics Listed Above)

4d. OTHER SEDIMENT CONTROL MEASURES

The straw bales at the inlet to UD-1 were not functional. It appeared as if deer at the site has scattered the bales (bales were not staked). The inlet to UD-1 (undisturbed drainage bypass) was partially blocked and some coal fines/sediment were deposited at the inlet area. It is difficult to separate the amount of fines in the inlet area into those deposited as a result of wind deposition and those the result of any runoff. NOV N88-15-1-1 was issued for failure to maintain the alternative sediment control measures in this area.

6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL

Approximately 130 tons of waste rock material has been removed from the waste pile at the site. The operator provided five receipts showing the material was trucked to the Utilite operation near Wanship. The operator stated that Utilite operation was interested in the reject coal if the test results could be maintained above 6000 btu/lb. The operator provided the results of a sample analysis of the material (dated 1-27-88). The sample was taken 1-22-88 and analyzed by Commercial Testing and Engineering Co., analysis report #57-25759. As received Btu/lb. was reported at 6648. Percent dry ash was reported as 35.25%

.16. ROADS b. DRAINAGE

The operator has properly handled snow removal at the site. All snow bladed from the area has been stored in an area that would report to the sedimentation pond during melt.

The operator was reminded to keep the drop drain at the lower access road free of material and insure at all times the drain is functional. At the time of this inspection some debris had accumulated at the drain. The operator stated he would clean the drain the following day.

Copy of this Report:

Mailed to: Jack Blonquist, John Kathman (OSM)
Given to: NOV File, Sue Linner, Joe Helfrich

Inspectors Signature and Number: R. Summers #154 Date: 2/22/88