



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: October 17, 1990
11:00 am to 1:00 pm

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground Surface Other
County: Summit County
Company Official (s): None
State Official(s): Randy Harden, Joe Helfrich
Partial: Complete: Date of Last Inspection: September 12, 1990
Weather Conditions: Clear, Warm
Acreage: Permitted 170 Disturbed 5.5 Regraded Seeded Bonded 5.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(X)	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	(X)
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/008

DATE OF INSPECTION October 17, 1990

1. PERMITS

The permit for the Boyer Mine was revoked on October 13, 1988. No mining related activity has occurred on that site since that date. Since the time of the last inspection, the operator has removed much of the mining equipment from the property.

Bond forfeiture proceedings are under way with the real property used for a collateral bond with the Division. In the interim, the Division has contracted reclamation work to commence at the Boyer Mine. The initial phase of the reclamation work to be conducted this fall will consist only of the backfilling of the portals and the installation of water bars in both access roads to the site to control erosion.

Upon receipt of funds from the eventual sale of the real property used as collateral, it is anticipated that complete reclamation of the site will occur by next fall.

The Division has completed Phase I reclamation activity on the site which consisted of backfilling of the portals at the mine site and the installation of water bars on the two roads approaching the mine facilities.

In general, the site appears to be in fair condition especially in consideration of the amount of time that the mine has remained idle. The backfilling of the portals and the installation of the water bars is complete. The total cost for the backfilling of the portals and the installation of the water bars on the site was \$5,052.50.

12. BACKFILLING AND GRADING

Portal backfilling was accomplished in accordance with the specifications of the contract awarded to High Mountain Builders. Backfill material was derived from the excess spoil and mine development waste materials located immediately on site. Spoil materials were utilized as backfill material up to the first 25 feet of the mine openings. Non-combustable mine development waste materials were then used to backfill the remaining 25 feet of the openings in accordance with MSHA requirements.

16. ROADS


b. DRAINAGE CONTROLS

Water bars were installed along the access roads to the mine facilities to ensure that drainage from these areas reports to the sediment pond. These water bars will be in place until such time as additional reclamation work for the site is accomplished next year.

Copy of this Report:

Mailed to: Brian Smith - OSM

Given to: Joe Helfrich - DOGM, Daron Haddock - DOGM

Inspectors Signature and Number: #13  Date: November 8, 1990