0023

File

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Valley Camp of Utah
Business Address: Trevor Whiteside, Chief Engineer Scofield Route Helper Utah 84526
Mine Name: Belina Permit Number: ACT/007/001
Type of Mining Activity: Underground ✓ Surface ___ Other Loadout
County: Carbon
Company Official(s): Steve Tanner
State Official(s): Tom Wright, Holland Shepherd
Inspection Date and Time: 12/17/85 230 315
Partial: ✓ Complete: ___ Date of Last Inspection: 11/20/85
Weather Conditions: Sunny Cold
Acreage: Permitted 6338 Disturbed 38 Regraded ___ Seeded ___ Bonded ___
Enforcement Action: ___

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS				
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS	✓			✓
d. OTHER SEDIMENT CONTROL MEASURES	✓			✓
e. SURFACE AND GROUNDWATER MONITORING				
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS	✓			✓
d. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: Act/007/001 Date of Inspection: 12/17/88

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

Heavy snow cover on site. Some runoff during inspection.

4(b) Contaminated snow placed close to berms on loadout area above sediment pond adjacent to highway. No contamination off permit area during this inspection. I advised Tanner than care should be taken in handle of this material.

4(c) The mine water pond at Belina mine portal was discharging during the inspection. Samples from this discharge was collected by Holland Shepherd. Sample results are not available at this time.

Contaminated snow from the pad is store between pad and sediment pond. A snow blower was working on removal of snow from the sediment pond access road during this inspection. Surface of the sediment pond was frozen with ice level appearing to be just below the discharge level.

16(b) A grader was cleaning the drainage ditch for the Class I access road during this inspection. Runoff from the road was flowing in the ditch. This flow was not running off the disturbed area.

Copy of this Report:
Mailed to: Trevor Whiteside Donna Griffin
Given to:

Inspectors Signature and Number: Thomas W Wright #8

0365Q 1-2