1751 QUARTERLY INSPECTION OF SEDIMENT PONDS

DATE INSPECTOR(S)	POND NO.	EMBANKMENT SEEPAGE	INTERIOR EROSION	SPILLWAY CONTINUITY	INLET-OUTLET EROSION	SEDIMENT LEVEL	SPILLWAY CLOGGING	SLOPE MOVEMENT	DEWATERING CLOGGING	CONSTRUCTED CAPACITY
1ST Q PRETTYMAN &	1	?	NONE	OK	OK	OK	OK	[illegible]	OK	2.52 A.F.
TANNER	2	OK	OK	OK						0.48 "
MARCH 30, 1987	3	OK	OK	OK						2.35 "
	4	—	—	—	—	—	—	—	—	11.20 "
	5	OK	OK	OK	OK	OK	OK	OK	OK	250 GPM

COMMENTS

1 FACE COVERED WITH SNOW 2"-3"

4 UNDER DEEP SNOW (INACCESSIBLE) TOE OF SPILLWAY NEEDS RUBBER BELT INSTALLED

2ND Q PAPPAS &	1	NONE	NONE	OK	NONE	OK *	NONE	NONE	NONE
TANNER	2	NONE	NONE	OK	NONE	OK *	NONE	NONE	NONE
JUNE 24, 87	3	NONE	NONE	OK	NONE	OK *	NONE	NONE	NONE
	4	NONE	NONE	REPAIR NEEDED	NONE	OK	NONE	NONE	NONE
	5	NONE	NONE	OK	NONE	OK	NONE	NONE	N/A

COMMENTS

*1 CHECK WHEN DRY

*2 CHECK WHEN DRY

*3 CHECK WHEN DRY

4 REPAIRS STARTED 6-25-87

3RD Q PAPPAS &	1	NONE	NONE	OK	OK	OK	OK	OK	OK
TANNER	2	NONE	OK	OK	OK	OK	OK	OK	OK
JULY 13, 87	3	NONE	OK	OK	OK	OK	OK	OK	OK
	4	NONE	NONE	OK	OK	OK	OK	OK	OK
	5	NONE	OK	OK	OK	OK	OK	OK	OK

COMMENTS

4TH Q TANNER	1	NOT ACCESSIBLE UNDER SNOW							
12/19/87	2								
	3								
	4								
	5	NONE	NONE	OK	OK	OK	OK	OK	OK

COMMENTS

RECEIVED FEB 04 1988 OIL, GAS & MINING

0003