0014

No orig. mine file
cc L Braxton

Southern Utah Fuel Company
P.O. Box P
Salina, Utah 84654
(801) 529-7428

Division of
Coastal States
Energy Company

RECEIVED
AUG 14 1986
DIVISION OF
OIL, GAS & MINING

Act/007/005
#9

August 12, 1986

Dr. Dianne R. Nielson
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Dear Dr. Nielson:

For your information, please find enclosed a copy of Southern Utah Fuel Company's quarterly sediment pond inspection report conducted August 12, 1986.

Sincerely,
SOUTHERN UTAH FUEL COMPANY

Mike Davis

Mike Davis
Construction Engineer

MD:cfc

Enclosure

MD 2/8/84

RECEIVED
AUG 14 1986
DIVISION OF
OIL, GAS & MINING

SOUTHERN UTAH FUEL COMPANY

Sediment Pond Quarterly Inspection Report

Inspector Mike Davis Date 8-12-86

1. Dam Structural Weakness

   A. Cracks or scarps on crest None Observed

   B. Cracks or scarps on slope None Observed

   C. Sloughing or bulging on slope None Observed

2. Major Erosion Problems None Observed

3. Surface Movements of Surrounding Slopes None Observed

4. Visible Sumps or Sinkholes in Slurry Surface None Observed

5. Clogging

   A. Spillway channels and pipes None Observed

   B. Decant system Decanting sediment pond at appr. 5 gal/min. Water samples taken 7-28-86 and 8-12-86

C. Diversion ditches None observed

6. Seepage (Specify Location, Color and Approximate Volume)
None Observed

7. Other Comments