0068

PLATEAU MINING COMPANY

A Subsidiary of Getty Mineral Resources Company
P. O. Drawer PMC Price, Utah 84501
Telephone (801) 637-2875

TO: TOM PORTLE

June 11, 1981

File Route Copy SP
ACT/007/006

Mr. Tom Portle
Division of Oil, Gas and Mining
1588 West North Temple
Salt Lake City, UT 84116

DIVISION OF
OIL, GAS & MINING

RE: LETTER OF CONCERN DATED JUNE 8, 1981

Dear Mr. Portle;

In response to your letter, I would like to outline, to you, the status of the items of concern.

The area south of the conveyor will be taken care of by July 1. The roadway will be sloped in toward the conveyor. A channel will be directed under the conveyor from the paved road approximately every 300 feet. This channel will be either lined with asphalt or with rip-rap and will continue across the road on the south side of the conveyor and down the slope to the drainage ditch. Please refer to Exhibit A enclosed for detail of drainage.

The ditch in question will be well established and rip-rapped adequately to prevent erosion.

The rills and gullies which were previously repaired have been seeded.

We have been working on the raptor question since receiving the April 21, 1981, letter. You will receive a response on this item by June 19.

If you have any further questions, please let me know.

Sincerely,

PLATEAU MINING COMPANY

Ben Grimes
Engineering and Reclamation Specialist

JUN 23 1981
LCS

BG/gd
enc.

cc: F.J. Tucker
Dan Price
Steve Rigby
Joe Ronan
Alden Pierce

EXHIBIT A



PLAN VIEW
N.T.S.



PROFILE VIEW
N.T.S.