0026

File
ACT/007/006
Folder No. 3
~~Copy to Wayne~~

PLATEAU MINING COMPANY

A Subsidiary of Getty Mining Company
P.O. Drawer PMC Price, Utah 84501
Telephone (801) 637-2875

RECEIVED
SEP 02 1983
DIVISION OF
OIL, GAS & MINING

August 31, 1983

Mr. James Smith
Division of Oil, Gas and Mining
4241 State Office Building
Salt Lake City, Utah 84114

JIM
SEP 02 1983

RE: Corner Canyon Breakout Fan Installation

Dear Mr. Smith:

We are proceeding with construction of the breakouts and fan installation. At this time, we have broken out Entries 1, 2 and 4. The pad has been excavated to grade, and we are close to starting concrete work.

Our engineers are considering not connecting the pad with Entry No. 2 breakout. This is because of several considerations: less environmental disturbance, less expense and access to the fan might be possible through Entry No. 4; which eliminates the need for the connection.

When the final details have been worked out with the Mine Safety and Health Administration for access through the fan housing located in Entry No. 4, we can make the final decision on the connection. This will likely be next year.

If you have any questions, don't hesitate to call.

Sincerely,

PLATEAU MINING COMPANY

Ben A. Grimes
Environmental Coordinator

BAG:sd