Document Information Form

Mine Number: C/007/006

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: MAY 25, 1984

Explanation:

INSPECTION MEMO TO COAL FILE

cc:

File in:
C/ 007, 006, Internal
Refer to:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Date _____ For additional information

May 25, 1984

Inspection Memo
to Coal File:

RE: Plateau Mining Company
Starpoint Mine
ACT/007/006, Folder #7
Carbon County, Utah

On May 16, 1984, a partial inspection was conducted at Plateau Mining's Starpoint Mine by Mining Field Specialist Tom Wright. This was a follow-up to check on NOV N84-4-7-6, #1,2,4,5, and 6 of 6 issued on April 24, 1984, by Dave Lof, Mining Field Specialist. Ben Grimes of Plateau was contacted and accompanied the inspector.

N84-4-7-6, 1 of 6

Failure to follow approved plans (diversion ditch north of refuse.) The operator has installed a culvert for trucks to pass over and drainage to pass to Sediment Trap #9. Riprap has been piled at this ditch for future use.

N84-4-7-6, # 2 of 6

Failure to follow approved plans (drainage from the preparation plant to Sediment Pond # 5).

No processing water from the preparation plant was being pumped on this date. A sump for the processing water has been constructed inside the refuse area and plans are being formulated for permanent slurry cells. Sediment pond #5 was dredged and the dredged material was placed inside the refuse area. Additional work removing material from around the standpipes will be done according to Mr. Grimes. It appears that the water from Pond # 5 was pumped into Pond #6

N84-4-7-6 # 4 of 6

Failure to maintain a Class II road (Sediment Trap 5 to #1 Mine)

Water bars have been constructed routing the drainage to an inside ditch which drains into the sediment trap. Sections of this ditch are extremely rough and may require additional work.

N84-4-7-6 # 5 of 6

Failure to maintain sediment controls (old #2 Mine Portal Road)

The operator has some grading along the road. No ponding ver, this area bears watching during wet w

N84-4-7-6, # 6 of 6

Failure to mainte ne and noncoal waste bin area).

File in:
☐ Confidential
☐ Shelf
☐ Expandable
Refer to Record No 0020 Date
In C/ 007, 006, Internal
For additional information

May 25, 1984

Inspection Memo
to Coal File:

RE: Plateau Mining Company
Starpoint Mine
ACT/007/006, Folder #7
Carbon County, Utah

On May 16, 1984, a partial inspection was conducted at Plateau Mining's Starpoint Mine by Mining Field Specialist Tom Wright. This was a follow-up to check on NOV N84-4-7-6, #1,2,4,5, and 6 of 6 issued on April 24, 1984, by Dave Lof, Mining Field Specialist. Ben Grimes of Plateau was contacted and accompanied the inspector.

N84-4-7-6, 1 of 6

Failure to follow approved plans (diversion ditch north of refuse.) The operator has installed a culvert for trucks to pass over and drainage to pass to Sediment Trap #9. Riprap has been piled at this ditch for future use.

N84-4-7-6, # 2 of 6

Failure to follow approved plans (drainage from the preparation plant to Sediment Pond # 5).

No processing water from the preparation plant was being pumped on this date. A sump for the processing water has been constructed inside the refuse area and plans are being formulated for permanent slurry cells. Sediment pond #5 was dredged and the dredged material was placed inside the refuse area. Additional work removing material from around the standpipes will be done according to Mr. Grimes. It appears that the water from Pond # 5 was pumped into Pond #6

N84-4-7-6 # 4 of 6

Failure to maintain a Class II road (Sediment Trap 5 to #1 Mine)

Water bars have been constructed routing the drainage to an inside ditch which drains into the sediment trap. Sections of this ditch are extremely rough and may require additional work.

N84-4-7-6 # 5 of 6

Failure to maintain sediment controls (old #2 Mine Portal Road)

The operator has closed the gap in the berm and done some grading along the road. No ponding of water was evident this date however, this area bears watching during wet weather.

N84-4-7-6, # 6 of 6

Failure to maintain Class II road (Road between #1 Mine and noncoal waste bin area).

No erosion was occurring on this date and no ponding was evident. This area will need to be closely monitored. Pictures were taken of all the area inspected and results found will be presented to Inspector Lof for his evaluation.

Tom Wright TW
Mining Field Specialist

TW:re

cc: Jodie Merriman, OSM
Ben Grimes, Plateau
Sue Linner, DOGM
Joe Helfrich, DOGM
David Lof, DOGM

Statistics: See Trail Mountain Coal Mine memo dated May 25, 1984
90410