0013

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: PLATEAU MINING COMPANY
Business Address: P.O. DRAWER PMC, PRICE, UTAH 84501
Mine Name: STAR POINT Permit Number: ACT/007/006
Type of Mining Activity: Underground ✓ Surface ___ Other ___
County: CARBON
Company Official(s): MANCO COPINGA AND BEN GRIMES
State Official(s): BILL MALENCIK AND PAMELA GRUBAUGH-LITTIG
Inspection Date and Time: MAY 7, 1987 FROM 9:15 A.M. TO 1:00 P.M.
Partial: ✓ Complete: ___ Date of Last Inspection: APRIL 1, 1987
Weather Conditions: SUNNY AND WARM (ABOUT 70°)
Acreage: Permitted 5225 Disturbed 221.6 Regraded ___ Seeded ___ Bonded 221.6
Enforcement Action: ___

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS				
3. TOPSOIL	✓			
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS	✓			✓
d. OTHER SEDIMENT CONTROL MEASURES	✓			
e. SURFACE AND GROUNDWATER MONITORING	✓			✓
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	✓			
7. COAL PROCESSING WASTE	✓			✓
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS				
d. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES	✓			✓
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				
19. Other	✓			✓

INSPECTION REPORT
(Page 2)

Permit Number: ~~ACT~~/007/006 Date of Inspection: 5/7/87

COMMENTS

(Comments are Numbered to Corresoond with Topics Listed Above)

4b. The "undisturbed drainage" behind the Lion Deck shop was operable. The ditch had been maintained recently.

4d. The ~~pipe~~ culvert (long downspout) that had been the reason for violation #N-87-9-3-1, has been permanently repaired below the Lion Deck parking pad.

16e. The road from the main yard to the bone yard (near the "Old #1 Mine) has recently been bladed. Waterbars are operable. The ditch along the inside of the road has been cleaned and maintained.

19. I checked the mine sequence maps in the office and noted ~~that~~ ~~the~~ where Plateau is mining. The longwall is in the Hattie seam, there is the room and pillar operation in Mudwater Canyon in the Thick Seam. All mining is being conducted within the approved mine permit area.

6. Rocks and soil material from spring maintenance of the Lion Deck Road (Season highwall slumping) are presently stored at the switchback of the Lion Deck Road. The material ~~has~~ is surrounded by a berm for containment.

Copy of this Report:
Mailed to: DONNA GRIFFIN (OSM) and Ben Grimes (PMC)
Given to: ~~John Whitehead~~ and Jo Helfrich

Inspectors Signature and Number: [signature], 5/8/87, #20

365Q 1-2