INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 3/7-8

Please number comments to correspond with topics on previous page.

7. Remove plates on primary and emergency spillway oil skimmers and meet approved trash rack and anti vortex device designs
8. No plans found for primary spillway. Primary spillway should be modified to meet approved trash rack and anti vortex device designs.
9. Installed as shown on approved drawings.

7. Coal processing Waste: The operator was requested to submit to the division certified quarterly inspection reports including appearances of instability, structural weakness, and other hazardous conditions immediately following regular inspections. A verification

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 3/7-8

Please number comments to correspond with topics on previous page.

that the specialist is experienced in the construction of similar earth and waste structures is required in the first quarterly inspection report submitted to the Division in 1991.

8. Noncoal waste: The operator is required to store noncoal wastes in a controlled manner in a designated portion of the permit area. It is suggested that the operator ~~provide~~ propose a program which will help alleviate non-coal waste ~~prob~~ problems with plugged culverts etc. General maintenance of trash racks and and culvert inlets ~~appeared~~ was the lacking as evidenced by N.O.V. 95-25-3. A better maintenance plan would help alleviate future N.O.V.'s.

Copy of report mailed to Ben Grimes / Oppens-Plateau; Brian Smith OSM

Copy of report given to Joe Helfrich / DOGM

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE