0051

File ACT/007/006 - 93B

CYPRUS
Plateau Mining

Cyprus Plateau Mining Corporation
P.O. Drawer PMC
Price, Utah 84501
(801) 6327-2875

May 18, 1993

Ms. Pamela Grubaugh-Littig
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RECEIVED
MAY 20 1993
DIVISION OF
OIL GAS & MINING

Dear Ms. Littig,

Re: Minor Modification

The enclosed maps show a minor modification we are asking for to eliminate a continual problem at ditch 74B. The original ditch was located behind two buildings that have now been removed. The ditch was very flat and silted in during most storms creating a maintenance problem.

Now that the buildings are gone, we would like to shorten the ditch which will help prevent siltation. The ditch will now discharge directly into Sediment Pond No. 9. Riprap will be placed in the pond at the discharge end of the ditch to prevent erosion of the pond side slope; the riprap will have a D_{50} of 1.0 ft. The ditch will have the same dimensions as the original, so there is no need for design changes.

Three revised copies of Maps 731.720 are included showing the revised ditch, Map 731.720e also shows the ditch and three revised copies of it are included. One copy of each map has the ditch highlighted to help you located the change.

If you have questions please contact me.

Respectfully,

Ben Grimes
Environmental Coordinator

File: ENV 2-5-2-1-1-2
ENV 2-5-2-16-33
Chrono: BG930507