0002

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Job

inspection report

Permit No. ACT/007/007

Inspection Date 12/8/87

Permittee/Operator Name Kaiser Coal Corporation

Business Address P.O. Box D Sunnyside, Utah 84539

City Sunnyside State Utah Zip 84539

Mine Sunnyside Complex ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) Barry Grosely

State Official(s) Jim Fricke & Bill Malencik

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 11:45 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/19/87 Weather conditions Clear 35°F

Acreage 4,535 ☒ Permitted 287.4 ☒ Disturbed ☐ Regraded ☐ Seeded 287.4 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a — Stream channel diversions	☐	☐	☐	☐
b — Diversions	☐	☐	☐	☐
c — Sediment ponds and impoundments	☒	☐	☐	☒
d — Other sediment control measures	☐	☐	☐	☐
e — Surface and groundwater monitoring	☒	☐	☐	☒
f — Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 12/8/87

Please number comments to correspond with topics on previous page.

2. Stream buffer zone signs were noted along Grassy Trail Creek. Mine property identification signs were noted.

4c. The Coarse Refuse Tve Pond and Surface Facilities Pond were inspected. Sediment level in the Coarse Refuse Pond may be above the design level. The marker could not be seen, although this may have been due to the water level and the slight ice cover. The pond is sized to contain the 100 year 24 hour runoff event and ~~should be~~ is functional at this time. The operator was advised to monitor the pond sediment level when the ice cover dissipates.

4e. Water monitoring data for the 3rd quarter was reviewed and the operator is in compliance with the approved monitoring plan.

Copy of report mailed to ~~D. Griffin~~ Brian Smith (OSM) (OSM) & Barry Grosely (KCC)

Copy of report given to J. Helfrich & J. Whitehead

Inspector's signature Jim Fricke 12/9/87 No. 22

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE