0057

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Bill got

inspection report

Permit No. ACT/007/007

Inspection Date 2/16-17/88

Permittee/Operator Name Kaiser Coal Corp.

Business Address P.O. Box D

City Sunnyside State Utah Zip 84539

Mine Sunnyside ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut.

Company Official(s) Barry Grosely

State Official(s) Wm. J Malencik. (Daron Haddock 2/16/88)

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 1/7/88 Weather conditions

Acreage 1495 ☐ Permitted 310 ☐ Disturbed ☐ Regraded ☐ Seeded 287 ☐ Bonded

Enforcement Action NOV 88-26-9-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☐	☒	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☒	☐	☐	☒
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 2/16-17/88

Please number comments to correspond with topics on previous page.

NOV 88-26-9-1 was issued to the permittee for three blocked culverts. Please refer to the discussion & description.

Permits. Final approval of the PAP Amendment for the as built plans on the coarse refuse toe pond was granted on 1/11/88. Permit documents reviewed & no problems detected.

Diversions. Three culverts were plugged. Ten photos were taken as additional evidence of conditions existing on the aforementioned culverts at the time of inspection. Culvert #1 as listed on the violation has a problem with the inlet and only a trickle of water is coming out of the outlet. This culvert lies under the Carbon County Railroad tracks and in an undisturbed drainage. Currently because of the culvert failure an unauthorized impoundment has formed. The impoundment by pacing is about 140' long width at the embankment/culvert inlet 50' and 20' at the head. The culvert outlet is 36" with a 21" opening. Water is seeping below the outlet from a source that cannot be detected from usual observations. The high water level on the impoundment is 29" above the level

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 2/16-17/88

Please number comments to correspond with topics on previous page.

existing on 2/17/87. The depth to the bottom of the impoundment could not be estimated because of murky nature of the water. A pump worker estimated the remaining depth at about 4'. The pump was operational at the time of inspection on both days. Also an air compressor was at the impoundment site. The operator has in the opinion of this inspector making a positive effort to drain the impoundment so that the problem could be corrected.

Culvert #2: Drains a small area estimated at less than 1/4 of an acre. The inlet has been covered with debris & sediment and could not be located. The culvert is 18" in diameter and the outlet was clean. The culvert is immediately above the new sediment pond. A small amount of water has overflowed across the tracks & exited into the same channel where the culvert is located, terminating into a sediment pond.

Culvert #3: Culvert 18" in diameter on the west end of the refuse pile is plugged with ice, sediment & coal refuse. No evidence of any erosion associated with this culvert

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 2/16-17/88

Please number comments to correspond with topics on previous page.

Reviewed the paperwork associated with
Sediment Pond Inspection
Refuse Pile Inspections
Water Monitoring
and found no problems.

Copy of report mailed to SLC - Brain Smith, OSM, Joe Helfrich DOGM.

Copy of report given to Barry GROSELY, KCC; PFO

Inspector's signature [signature] No. 26.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE 2/17/88.

an equal opportunity employer