0004

U. S. Department of Labor

Mine Safety and Health Administration
P.O. Box 25367
Denver, Colorado 80225-0367

Coal Mine Safety and Health
District 9

RECEIVED
MAY 06 1996
DIV. OF OIL, GAS & MINING

MAY - 2 1996

Robert M. Burnham
President
Sunnyside Coal Company
P. O. Box 99
Sunnyside, UT 84539

Orig. to Daron #2
Copy ACT/007/035
Copy ACT/007/007 #2
Copy Joe and File

RE: Sunnyside Surface Operations
ID No. 42-01813
West Slurry Cell Impoundment
ID No. 1211-UT-09-01813-01
Coarse Refuse Pile
ID No. 1211-UT-09-01813-02
First Quarter 1996 Inspection Report

Dear Mr. Burnham:

This is in response to the subject report dated April 1, 1996, received from Sunnyside Cogeneration Associates. The report has been reviewed by MSHA personnel and cannot be accepted for the mine file as submitted.

MSHA does not require quarterly reports. We do require annual reports that must be separate for each impoundment. These reports must identify each impoundment by it's MSHA identification number, such as 1211-UT-09-01813-01.

Attached are two letters from this office to you, dated August 16, 1995, and October 20, 1995, which requested your assistance in correcting this error. If we can be of any help in resolving this problem please contact Mike Stanton, of this office, at (303) 231-5458, ext. 113.

Sincerely,

John A. Kuzar
District Manager

Enclosure

cc: Daron Haddock
Division of Oil, Gas, and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Danny Mattingly
General Manager
Sunnyside Cogeneration Ass.
P. O. Box 10
East Carbon, UT 84520

JC 10-20-95

Surname	Date
[illegible]	10/20/95
Slanton	10-20-95
Slanton for RC	10-20-95
Kney	10/2

Coal Mine Safety and Health
District 9

OCT 20 1995

Robert M. Burnham
President
Sunnyside Coal Company
P. O. Box 99
Sunnyside, UT 84539

RE: Sunnyside Surface Operations
ID No. 42-01813
West Slurry Cell Impoundment
ID No. 1211-UT-09-01813-01
Coarse Refuse Pile
ID No. 1211-UT-09-01813-02
Third Quarter Inspection Report

Dear Mr. Burnham:

This is in response to Sunnyside Coal Company's letter and subject report dated October 4, 1995, for the referenced surface impoundments. The report has been reviewed by MSHA personnel, and cannot be accepted for the mine file, as submitted.

Enclosed is a copy of our letter to you dated August 16, 1995, which states that these impoundments must be properly identified by MSHA I.D. Number in all correspondence. Also, for filing purposes, there must be a separate report for each impoundment. We have also included herewith a file copy of a Sunnyside Impoundment Report dated March 30, 1993, which IS correct and complete. Please use this format to resubmit your quarterly report and all future impoundment reports. Thank you for your cooperation.

Sincerely,

John A. Kuzar
District Manager

Enclosures

cc: Price SDO
Price #2 FO
EC File
Imp File 83-24
D9 Chron 10-11-95 #7
MSHA:WP:(42-01813.AIR):sg

RC 8-15-95

Sheldon 8-15-95
Sheldon for RC 8-15-95

Coal Mine Safety and Health
District 9

AUG 16

SURFACE MINE FILE
DATE FWD. 8/17/95
INITIALS SM

Robert M. Burnham
President
Sunnyside Coal Company
P. O. Box 99
Sunnyside, UT 84539

RE: Sunnyside Surface Operations
ID No.42-01813
West Slurry Cell Impoundment
ID No. 1211-UT-09-01813-01
Coarse Refuse Pile
ID No. 1211-UT-09-01813-02
Inspection Report

Dear Mr. Burnham:

This is in response to Sunnyside Cogeneration Associates' letter and 2nd Quarter inspection report dated July 26, 1995, for the above-referenced impounding structures at the subject mine. The report has been reviewed by MSHA personnel and made part of the mine file. Please cite the MSHA identification numbers on all correspondence regarding these impoundments. Thank you for your cooperation in this regard.

Sincerely,

151 WPK/ for

John A. Kuzar
District Manager

cc: Alane E. Boyd, P.E.

bcc: Price SDO
Price #2 FO
EC File
Imp File 80-14
D9 Chron 8-1-95 #1
MSHA:WP:(42-01813.AIR):sg