UTAH
NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/013
Inspection Date OCT 11, 1990

Permittee/Operator Name INTERMOUNTAIN POWER AGENCY
Business Address RM 1164, 111 NORTH HOPE ST, LOS ANGELES, CA
City LOS ANGELES State CA Zip 90051
Mine HORSE CANYON ☐ Surface ☒ Underground ☐ Other
County CARBON State UTAH
Company Official(s) BILL ENGELS
State Official(s) TOM MUNSON
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 16:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 9/7/90 Weather conditions SUNNY
Acreage ☐ Permitted 63.6 ☒ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. 007/013

Inspection Date 10/11/90

Please number comments to correspond with topics on previous page.

4b Diversions: The undisturbed diversion in the vicinity of the waste rock area has been experiencing many storms this fall. Maintenance of this diversion has been on-going. In areas of lesser slope, deposition of sediments is occurring and on steeper slopes riprap failure has been noted. The maintenance of this diversion will require repair of riprap and removal of sediments where needed. The operator will potentially want to discuss design changes if maintenance of this diversion becomes too intensive.

The access road to the upper pad is bermed at the lower end to route drainage into a sediment pond. Because of reclamation, truck traffic has made the berm inoperable. In its place will be put a swale to carry runoff to the pond. This was suggested as a remedial measure to the current

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. 007/013

Inspection Date 10/11/90

Please number comments to correspond with topics on previous page.

situation ~~was~~ of increased traffic flow and berm maintenance. No evidence of offsite drainage was noted.

12. Backfilling and Grading. - Several areas of backfilling have occurred and materials are being end dumped and sorted, so no lumber will end up in the final piles. This was inspected and found to be acceptable.

4d Other sediment control measures - All silt fences and straw bales were in place and in good repair. Temporary sediment control measures were in place in Horse Creek below any disturbance adjacent to the Creek.

Copy of report mailed to John Kathman (OSM) Joe Helfrich (DOGM)

Copy of report given to Price Field Office

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE