0004

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

007/016 #5

inspection report

Permit No. ACT/007/016

Inspection Date 11/12/87

Permittee/Operator Name BEAVER CREEK COAL CO.

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine GORDON CREEK #2 & #7 ☐ Surface ☒ Underground ☐ Other

County CARBON State UTAH

Company Official(s) DAN GUY

State Official(s) R.V. SMITH

Time of inspection 2:30 ☐ a.m. ☒ p.m. to 3:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection [redacted] 10/22/87 Weather conditions PARTLY CLOUDY, 50°

Acreage 2289 ☒ Permitted 9 ☒ Disturbed ☐ Regraded ☐ Seeded 9 ☒ Bonded

Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☒	☐	☐	☒
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 11/12/87

Please number comments to correspond with topics on previous page.

2. Disturbed area perimeter sign at Right Fork Bryner Canyon has been replaced

4c. Both the upper and lower sediment ponds contained water at a level approximately 6 to 8 feet below the decant.

4d. New straw bales have been installed in drainage ditches surrounding the upper Topsoil storage pile.

16b. Drainage ditches on both sides of haul road had been recently cleaned.

Copy of report mailed to Dan Guy, BCCC; Brian Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Richard V. Smith 11-24-87 No. 19

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE