0006

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/016
Inspection Date 10/22/87

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1278
City Price State Ut. Zip 84501
Mine Gordon Creek 2&7 ☐ Surface ☒ Underground ☐ Other
County Carbon State Ut.
Company Official(s) Dan Guy
State Official(s) Bill Malencik
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 10/1/87 Weather conditions Clear/Cool/Mine Site Dry
Acreage 2289 ☐ Permitted 9 ☐ Disturbed — ☐ Regraded — ☐ Seeded 9 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016.

Inspection Date 10/22/87

Please number comments to correspond with topics on previous page.

Signs & Markers: Required signs & markers were observed and meet the regulation & MRP.

Topsoil. Topsoil areas contained good vegetal cover & were also protected by a berm around the topsoil pile.

Stream Channel Diversion. Stream channel diversions were open. The half round above sediment pond #2 had a small accumulation of sediment at the upper end. While this sedimentation notation is included for the record it should not be construed as implying a violation exists. However, it is being documented for the benefit of the operator as a possible preventative maintenance item.

Other Sediment Control Measures. New strawbales were along the haul road.

Noncoal Waste. The mine site was clean & the noncoal waste is being handled as outlined in the MRP.

Road/Drainage Control. The haul road drainage ditches were recently cleaned & reshaped.

Copy of report mailed to SLC: Brain Smith, OSM; Joe Helfrich, DOGM.

Copy of report given to Dan Guy, Beaver Creek Coal Co. on 10/28/87

Copy for price file:

Inspector's signature Jim J. Smalenik 10/30/87 No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE