File

0039

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: BEAVER CREEK COAL COMPANY
Business Address: P.O. BOX 1378 PRICE, UTAH 84501
Mine Name: GORDON CREEK #2 & #7 Permit Number: ACT/007/016
Type of Mining Activity: Underground X Surface ___ Other ___
County: CARBON
Company Official(s): KEN FLECK
State Official(s): JOHN WHITEHEAD, RICHARD SMITH
Inspection Date and Time: 3/25/87 ; 3:00 pm
Partial: X Complete: ___ Date of Last Inspection: 2/19/87
Weather Conditions: PTLY. CLDY, SNOW ON SITE
Acreage: Permitted 2289 Disturbed 9 Regraded ___ Seeded ___ Bonded 9
Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS	X			
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS	X			X
d. OTHER SEDIMENT CONTROL MEASURES	X			
e. SURFACE AND GROUNDWATER MONITORING	X			X
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS				
c. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

STATE OF UTAH
Oil, Gas & Mining

INSPECTION REPORT
(Page 2)

Permit Number: ACT/007/016

Date of Inspection: 3/25/87

COMMENTS

(Comments are Numbered to Corresoond with Topics Listed Above)

#4b. The site was muddy from snowmelt. Disturbed area drainage ditches were functioning properly, routing flows into the lower sediment pond.

#4d. Operator was reminded of committment to replace, as part of routine maintenance, straw bales along mine access road by March 31, 1987.

Copy of this Report:
Mailed to: D. Griffin (OSM), D. Guy (BCCC)
Given to: J. Helprich, J. Whitehead

Inspectors Signature and Number: Richard V. Smith 3/26/87

0365Q 1-2