3-30-88

0025

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/016

Inspection Date 3/14/88

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State Ut. Zip 84501

Mine Gordon Creek No. 2/7 Mine ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Jay Marshall

State Official(s) Jim Fricke

Time of inspection 10:30 ☒ a.m. ☐ p.m. to 12:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 1/7/88 Weather conditions Clear, Cool

Acreage 2289 ☒ Permitted 9 ☒ Disturbed ☐ Regraded ☐ Seeded 9 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☒	☐	☐	☒
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 3/14/88

Please number comments to correspond with topics on previous page.

4a.) The Sweet's Canyon water supply pond and associated Gordon Creek diversion were inspected. Appropriately 8 inches of snow was on the ground, therefore specific observations on channel capacity, riprap and channel sideslopes were difficult to achieve. Diversion slope measurements were verified and the existing channel slope is in compliance.

Copy of report mailed to Dan Guy, BCCC

Copy of report given to Brian Smith (OSM) & Joe Helfrich (DOGM)

Inspector's signature Jim Fricke 3/18/88 No. 22

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE