7-25-89
2025

0013

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jdh RUS

inspection report

Permit No. ACT/007/016
Inspection Date July 13, 1989

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State UT Zip 84501
Mine Gordon Creek 2, 7 & 8 ☐ Surface ☒ Underground ☐ Other
County Carbon State UT
Company Official(s) Dan Guy
State Official(s) Bill Wagmach & Bill Malencik
Time of inspection 9:30 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection June 22, 1989 Weather conditions Clear & warm
Acreage 2289 ☒ Permitted 9 ☒ Disturbed ☐ Regraded ☐ Seeded 9 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☐	☐	☐	☐
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☐	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date July 13, 1989

Please number comments to correspond with topics on previous page.

GENERAL: DAN GUY (BCCC) & BILL MALENCIK (DOGM) PARTICIPATED IN THIS PARTIAL INSPECTION. GROUND CONDITIONS WERE MUCH FROM THE PREVIOUS STORM ACTIVITY ON 7/12.

4b DIVERSION: CULVERTS & DITCHES THROUGHOUT THE SITE APPEARED FUNCTIONAL; CLEANOUT HAD BEEN DONE PRIOR TO THIS INSPECTION ON THE 1½-ROUND CULVERT NE OF THE TOPSOIL STORAGE AREA.

4d. OTHER SEDIMENT CONTROLS: THE STRAW BALES ALONG THE HAUL ROAD APPEARED IN GOOD CONDITION & FUNCTIONING PROPERLY. WATER & SEDIMENT WAS EVIDENT AT MOST OF THESE STRUCTURES.

16d. ROAD MAINTENANCE: ALTHOUGH PRECIPITATION HAD RECENTLY OCCURRED, THE HAUL ROAD WAS STARTING TO PRODUCE DUST. MR. GUY WAS AWARE OF THE DUST CONTROL PROGRAM (WATERING) & IT WILL BE IMPLEMENTED AS NECESSARY.

18. SUPPORT FACILITIES: THE #8 MINE BELT STRUCTURE HAS BEEN INSTALLED TO THE HIGHWALL; BREAKOUT FOR #3 (RETURN) ENTRY SHOULD TAKE PLACE IN THE NEAR FUTURE.

Copy of report mailed to SLC: JOE HELFRICH/DOGM, BRIAN SMITH/OSM, DAN GUY BCCC

Copy of report given to FRO

Inspector's signature William A. Warnock No. 30

7/13/89

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049