0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/016
Inspection Date 7/5/90

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Gordon Creek 2, 4, & 8 ☐ Surface ☒ Underground ☐ Other
County Carbon State
Company Official(s) Dan Guy.
State Official(s) Bill Malencik & John Pappas
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 10:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection June 5 Weather conditions Clear/Warm
Acreage 2289 ☐ Permitted 18 ☐ Disturbed ☐ Regraded ☐ Seeded 18 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 7/5/90

Please number comments to correspond with topics on previous page.

General Comments. The mine was idle, no coal hauling was taking place and the environmental maintenance crew was performing routine maintenance

Topsoil. Suggested to the operator that
(1) some belt rollers stored adjacent to the #8 mine topsoil pile be moved to an appropriate storage area, and
(2) the siltfence on the topsoil pile by the number 2 mine be beefed up in places to prevent soil like material from encroaching on the topsoil pile

Sediment Ponds. The two sediment ponds contained water and were not discharging.

Revegetation. Observations made included the following
(1) The two reference areas had been staked and flagged and
(2) The outslope of the portal pad on #8 mine seeded last fall has a good stand of vegetation

Roads. Some straw bales for drainage control on the haul road were being replaced during the inspection.

Copy of report mailed to Bcc/ Dan Guy; OSM/ Brain Smith; DOGM/ Joe Helfrich

Copy of report given to filed PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

7/10/90.

DOGM/IR-2

an equal opportunity employer

11/86 001049