UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

0010

inspection report

Permit No. ACT/007/016
Inspection Date 5/6/91

Permittee/Operator Name Beaver Creek Coal Company (BCCC)
Business Address P.O. BOX 1378
City PRICE State UTAH Zip 84501
Mine GORDON CREEK 2/7 +8 ☐ Surface ☒ Underground ☐ Other
County CARBON State UTAH
Company Official(s) DAN GUY
State Official(s) HENRY SAUER
Time of inspection 11:30 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 4/25/91 Weather conditions Clear and Warm
Acreage 2289 ☒ Permitted 17.2 ☐ Disturbed ☐ Regraded ☐ Seeded 17.2 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 5/6/91

Please number comments to correspond with topics on previous page.

GENERAL COMMENTS: Dan Guy (BCCC) accompanied the undersigned inspector on this partial state inspection of the mine site. Weather conditions were clear and warm. Snow is still evident around the disturbance but it is presently melting.

3) Topsoil: Mr. Guy and myself discussed the need to revised the soil/spoil sampling plan within the permit. After review of the backfilling and grading plans for the #2 + #8 mines we agreed upon a basic sampling design. Since the #7 mine backfilling plan is still pending, we didn't dicuss a sampling plan for this mine. Mr. Guy will submit a request for a PAP amendment to change the original soil sampling plan. The amendment will describe the discussions we had on the date of this inspection.

4) Hydrologic Balance - Diversions: The diversion system on site appears to be handling the melt water. ~~Alt~~ ditches observed are clear and functioning well.

Copy of report mailed to Dan Guy (BCCC), John Kathmann (O.S.M.)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Henry Sauer No. 32

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE