0012

File 4/24

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Beaver Creek Coal Company
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: Gordon Creek #3 & #6 Mine Permit Number: INA/007/017
Type of Mining Activity: Underground X Surface ___ Other ___
County: Carbon
Company Official(s): Dan Guy
State Official(s): Phil Ralphs
Inspection Date and Time: 4/24/86 8:30-9:30am
Partial: X Complete: ___ Date of Last Inspection: 4/2/86
Weather Conditions: Cloudy & Cool
Acreage: Permitted 800 Disturbed 8.0 Regraded — Seeded — Bonded 28.0
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS	X			
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS	X			X
d. OTHER SEDIMENT CONTROL MEASURES				
e. SURFACE AND GROUNDWATER MONITORING				
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS	X			X
d. SURFACING				
e. MAINTENANCE	X			X
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: INA/007/017 Date of Inspection: 4/24/86

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENT:

- The purpose of this Inspection was to check on the measures implemented by the Operator to Abate NOV N86-8-7-1 which was issued by Division Inspector Tom Wright on 4/7/86.

The NOV was issued for "Failure to maintain sediment control to the extent possible to prevent additional contributions of sediment to streamflow."

The portion of the mine site to which the NOV applied was the "Discharge culvert for the sediment pond at Gordon Creek 3 and 6 mine." The action required to abate the NOV was to "Repair structure so that flow of any discharge can be regulated for sediment control."

The Operator (Mr. Guy) had the inlet of the culvert in question plugged and sealed with grout the day following the inspection (4/3/86), for which the NOV was issued. ... installed to act as a decant structure when the pond was constructed. The violation was issued because the sliding gate on the outlet of the culvert, which originally acted as a flow regulator and shut-off, was bent to the extent that it was no longer functioning as designed.

The ~~extra~~ measure inacted by the Operator of grouting and sealing the culvert, was deemed sufficient to abate the violation. The violation was terminated on 4/29/86 with an effective date of 4/3/86, the day ~~of actual~~ measure was inacted by the Operator.

1(a,b) & e) ROADS, DRAINAGE CONTROLS & MAINTENANCE:

- The Operator has just completed routine maintenance of roads and drainage ditches. All road drainage control measures are in good condition.

Copy of this Report:
Mailed to: Donna Griffin (OSM) and Dan Guy (BCCC)
Given to: Joe Helfrich ~~[illegible]~~, John Whitehead and Tom Wright (DOGM)

Inspectors Signature and Number: _____

0365Q 1-2

Inspection Report
(continuation sheet)

Page____of____

Permit Number:_____

Date of Inspection:_____

COMMENTS

Inspectors Signature, Number and Date:_____

0365Q 3