0009

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jah RVS

inspection report

Permit No. INA/007/017

Inspection Date Aug. 9, 1989

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State UT Zip 84501

Mine Gordon Creek 3 & 6 ☐ Surface ☒ Underground ☐ Other

County Carbon State UT

Company Official(s) None

State Official(s) Bill Wakmack

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection July 6, 1989 Weather conditions Partly Cloudy & warm

Acreage 666 ☒ Permitted 34.4 ☒ Disturbed 28 ☒ Regraded 28 ☒ Seeded 28 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☒	☐	☐	☐
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☒	☐	☐	☐
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations (fences)	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-1

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ~~ZN~~/007/017

Inspection Date Aug. 9, 1989

Please number comments to correspond with topics on previous page.

GENERAL: A PARTIAL INSPECTION WAS CONDUCTED AT THE GOLDEN CREEK 3&6 MINES WITHOUT REPRESENTATION FROM BCCC, HOWEVER, CONTRACT LABORERS WERE ON SITE. THE SITE WAS DRY, HOWEVER, EVIDENCE PRESENT DURING THE INSPECTION INDICATED A LARGE PRECIPITATION EVENT HAD RECENTLY OCCURRED. NO MEASUREMENTS OF THE EVENT WERE AVAILABLE. THE UPPER CELL OF THE SED POND & THE BASIN BELOW THE UPPER GATE CONTAINED WATER. REPAIRS WERE MADE TO THE DRAINAGES & SED CONTROLS PRIOR TO & DURING THIS INSPECTION, THEREFORE, ENFORCEMENT ACTION WAS NOT WARRANTED.

4b. DIVERSIONS: THE 24" CULVERT INLET EAST OF THE #3 MINE RECLAIMED AREA (ROAD CROSSING) HAD A CONSIDERABLE AMOUNT OF SEDIMENT & DEBRIS BUILT UP AT THE MOUTH OF THE CULVERT. THE DEBRIS &

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. UT/007/017

Inspection Date AUG 9, 1989

Please number comments to correspond with topics on previous page.

SEDIMENT WAS REMOVED TO FACILITATE THE DRAINAGE.

THE UNDISTURBED DRAINAGE BYPASS BELOW THE SITE HAD AN ACCUMULATION OF WEEDS IN THE INLET AREA, & WERE SUBSEQUENTLY REMOVED. NO EVIDENCE OF PLUGGING OR OVERTOPPING.

THE REMAINING DIVERSIONS (DITCHES) DID NOT SHOW ANY SIGNS OF SIGNIFICANT EROSION OR DEPOSITION. FOR THE MOST PART, RUNOFF WAS LIMITED TO THE EASTERN PORTION OF THE SITE.

4d. OTHER SED CONTROLS: SILT FENCES ALONG THE EASTERN SIDE OF THE ROAD CONTAINED WEEDS & SEDIMENT; WESTERN SILT FENCES DID NOT CONTAIN ANY DEBRIS OR WATER, NOR DID THEY INDICATE ANY PROBLEMS. WHERE REQUIRED, SEDIMENT & DEBRIS WAS REMOVED APPROPRIATELY.

Copy of report mailed to Joe Helfrich (DOGM), Brian Smith (OSM), Dan Guy (BCCC)

Copy of report given to PFO

Inspector's signature William A. Warmack 8/10/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE