0006

File Copy

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: North American Equities
Business Address: 1401 17th Street Denver, Col 80202
Mine Name: Blazon # 1 Permit Number: ACT/007/021
Type of Mining Activity: Underground ___ Surface ___ Other Inactive
County: Carbon
Company Official(s): none
State Official(s): Tom Wright, Holland Shepherd
Inspection Date and Time: 10-30-85 3:30 pm - 4:30 pm
Partial: ✓ Complete: ___ Date of Last Inspection: ___
Weather Conditions: cool breezy @ 45°F
Acreage: Permitted 4.65 Disturbed ___ Regraded ___ Seeded ___ Bonded ___
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS				
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				✓
c. SEDIMENT PONDS AND IMPOUNDMENTS	✓			✓
d. OTHER SEDIMENT CONTROL MEASURES				
e. SURFACE AND GROUNDWATER MONITORING				
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS				
d. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: ACT/007/021 Date of Inspection: 10-30-85

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

4b. Diversions: Ditches and berms require maintenance in several places on this site. Berm which borders ditch along west foot of refuse pile (on main pad) need strengthening. Berm and ditch channeling disturbed drainage off main pad to sediment pond requires maintenance at points where it crosses the road entering the pad and warehouse area. No disturbed runoff has bypassed controls at this time.

4c. Pounds and Impoundments: Sediment ponds on site contain normal water levels. Upper pond, the water level is approx. 3½ feet below discharge point. No discharge was detected as having taken place within the recent past.

Copy of this Report:
Mailed to: Alan Smith, Donna Griffin
Given to:

Inspectors Signature and Number: #9

0365Q 1-2