0008

File

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Beaver Creek Coal Company
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: C.U. Spur Prep Plant & Loadout Permit Number: ACT/007/022
Type of Mining Activity: Underground ___ Surface ___ Other Prep Plant & Loadout
County: Carbon
Company Official(s): Dan Guy
State Official(s): Phil Ralphs
Inspection Date and Time: 6/10/86 8:00 am - 11:00 am
Partial: ✓ Complete: ___ Date of Last Inspection: 5/22/86
Weather Conditions: Partly Cloudy & Mild
Acreage: Permitted 160 Disturbed 110 Regraded ___ Seeded ___ Bonded 110
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS	X			
3. TOPSOIL	X			
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	X			X
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS	X			X
d. OTHER SEDIMENT CONTROL MEASURES				
e. SURFACE AND GROUNDWATER MONITORING				
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS				
d. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: ACT/007/022 Date of Inspection: 6/10/86

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

HYDROLOGIC BALANCE: Diversions & Sediment Ponds:

- The undisturbed diversion, which, for the most part, encompasses the disturbed area was walked during this Inspection. No problems or concerns were noted with this diversion, nor the disturbed diversions which route runoff to the sediment Ponds.

- The sediment Ponds were also inspected at this time. No problems were noted with the ponds.

Copy of this Report:
Mailed to: Donna Griffin (OSM) Dan Guy (BCCC)
Given to: Joe Helfrich and John Whitehead

Inspectors Signature and Number: Philip M Grubbs #10, 6/10/86

0365Q 1-2

Inspection Report
(continuation sheet)

Page ____ of ____

Permit Number: _____

Date of Inspection: _____

COMMENTS

Inspectors Signature, Number and Date: _____

0365Q 3