0007 ✓10-13-87

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jph

inspection report

Permit No. ACT/007/022
Inspection Date September 28, 1987

Permittee/Operator Name Beaver Creek Coal Company
Business Address P.O. Box 1378
City Price State UT Zip 84501
Mine C.V. Spur (Prep Plant) ☐ Surface ☐ Underground ☒ Other
County Carbon State UT
Company Official(s) Dan Guy
State Official(s) Harold G. Sandbeck and John Whitehead
Time of inspection 4:00 ☐ a.m. ☒ p.m. to 6:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection August 27-31, 1987 Weather conditions Clear/Warm
Acreage 160 ☒ Permitted 110 ☒ Disturbed ☐ Regraded ☐ Seeded 110 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☐	☐	☐	☐
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☐	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date September 28, 1987

Please number comments to correspond with topics on previous page.

General Comments: Since the last inspection, Co-Op Mining Company has corrected the immediate drainage problem which effated C.V. Spur's drainage. However, construction still appears to be in progress on the Co-Op mine site.

2.) Signs and Markers: Signs have correct information and are up to date. Perimeter markers were seen during inspection.

4.b.) Diversions: A blockage in undisturbed drainage was corrected on site and verified before undersigned inspector left site. A culvert northeast from the pump house had been replaced.

4.c.) Sediment Ponds and Impoundments: Pond number 1, 5 and 6 inlets had been repaired with cement.

Copy of report mailed to Dan Guy, C.V. Spur and Brain Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Howard D. Sandvik October 2, 1987 No. 27

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE