7035 12.13.88 0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022
Inspection Date DEC. 6, 1988

Permittee/Operator Name BEAVER CREEK COAL CO.
Business Address P.O. BOX 1378
City PRICE State UT Zip 84501
Mine C.V. SPUR (LOADOUT) ☐ Surface ☐ Underground ☒ Other
County CARBON State UT
Company Official(s) DAN GUY
State Official(s) BILL WAKMACK
Time of inspection 2:00 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection NOV. 1, 1988 Weather conditions OVERCAST & COOL
Acreage 160 ☒ Permitted 108 ☒ Disturbed ☐ Regraded ☐ Seeded 160 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 12/6/88

Please number comments to correspond with topics on previous page.

GENERAL: DAN GUY (BCCC) ACCOMPANIED THE UNDERSIGNED INSPECTOR ON THIS PARTIAL INSPECTION. SITE CONDITIONS WERE DRY & APPEARED TO BE VERY STATIC. NO PROBLEMS WERE OBSERVED OR NOTED.

4b. DIVERSIONS

① AS DISCUSSED IN THE PREVIOUS INSPECTION REPORT (11/1/88), THE INLET AREA OF CULVERT C8 REQUIRED SOME ADDITIONAL RIPRAP. THE WORK HAS BEEN COMPLETED & SHOULD ALLEVIATE ANY FUTURE PROBLEMS.

② THE INLET AREA TO CULVERT C9 HAS BEEN CLEANED.

16d. ROAD MAINTENANCE

ALTHOUGH THE SITE IS VERY DRY, ALL OF THE HAUL ROADS WERE WATERED TO REDUCE FUGITIVE DUST.

Copy of report mailed to DAN GUY (BCCC); JOE HEFRICH (DOGM), BRIAN SMITH (OSM)

Copy of report ~~given~~ FILED to PFO

Inspector's signature William A. Warnack 12/6/88 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE