0014

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022

Inspection Date 2/9/88

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine C.V. SPUR (PREP. PLANT/LOADOUT) ☐ Surface ☐ Underground ☒ Other

County CARBON State UTAH

Company Official(s) DAN GUY

State Official(s) RICHARD SMITH, DAN DUCE

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 1/6/88 Weather conditions PARTLY CLOUDY, 45°

Acreage 160 ☒ Permitted 108 ☒ Disturbed ☐ Regraded ☐ Seeded 160 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☐	☐	☐	☐
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/[redacted]022

Inspection Date 2/9/88

Please number comments to correspond with topics on previous page.

4b. Culvert outlet below Topsoil stockpile has undergone routine preventative maintenance in the form of reshaping and rip-rap installation.

4c. Pond #5 inlet and outlet has undergone routine preventative maintenance in the form of reshaping and rip-rap installation.

13. Revegetation test plots have been installed on the coal refuse south of the topsoil stockpile. Test plots have been fenced, topsoil has been distributed and winter precipitation indicates a high likelihood of plant germination. Topsoil and refuse sampling has been conducted for material characterization. Chemical analyses data are pending.

Copy of report mailed to DAN Guy, BCCC

Copy of report given to BRIAN SMITH, OSM; JOE HELFRICH, DOGM

Inspector's signature Richard V. Smith 2-12-88 No. 19

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE