0014

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022
Inspection Date 2/23/90

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine C.Y Spur headout ☐ Surface ☐ Underground ☒ Other
County Carbon State Ut
Company Official(s) Dan Guy
State Official(s) Bill Malencik
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection JAN. 30, 1990 Weather conditions Clear/Cold/Dry Mine Site
Acreage 160 ☐ Permitted 108 ☐ Disturbed ☐ Regraded ☐ Seeded 108 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 2/23/90

Please number comments to correspond with topics on previous page.

General Comments. This partial inspection primarily involved checking environmental control measures at the loadout. All the snow had melted and the operator was performing spring maintenance work.

Topsoil. The topsoil piles had been scarified and seeded. The scarification was accomplished by a crawler tractor.

Diversions. The operator was replacing rip-rap on some of the culvert outlets. While the ditches showed evidence of runoff no significant erosion and/or depositions was observed.

Sediment Ponds. Pond 5&6 contained water and were not discharging.

The operator was repairing rills on the thickner pond. It did not contain water.

Refuse Pile. The south side of the refuse pile had recently been groomed. Slopes appear to be in line with the degree of slope as required in the MRP.

Copy of report mailed to { BCCC/DAN GUY
SLC For: OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to DFO

Inspector's signature Wm. J. Malenich No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

8/2/90

DOGM/IR-2 an equal opportunity employer 11/86 001049