0014

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Job page



# inspection report

Permit No. ACT/007/022
Inspection Date 3/13/91

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine C.V. Spur ☐ Surface ☐ Underground ☒ Other
County Carbon State Ut
Company Official(s) Dan Guy.
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 2/21/91 Weather conditions Overcast/Cool
Acreage 160 ☒ Permitted 108 ☒ Disturbed ☐ Regraded ☐ Seeded 108 ☒ Bonded
Enforcement Action None

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☒ | ☐ | ☐ | ☒ |
| 2. Signs and markers | ☒ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☒ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| — Stream channel diversions | ☒ | ☐ | ☐ | ☒ |
| — Diversions | ☒ | ☐ | ☐ | ☒ |
| — Sediment ponds and impoundments | ☒ | ☐ | ☐ | ☒ |
| — Other sediment control measures | ☒ | ☐ | ☐ | ☒ |
| — Surface and groundwater monitoring | ☒ | ☐ | ☐ | ☒ |
| — Effluent limitations | ☒ | ☐ | ☐ | ☒ |
| 5. Explosives | ☐ | ☐ | ☒ | ☒ |
| 6. Development waste and spoil disposal | ☒ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☒ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☒ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☒ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☒ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☒ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☐ | ☐ | ☒ | ☐ |
| 13. Revegetation | ☒ | ☐ | ☐ | ☒ |
| 14. Subsidence control | ☐ | ☐ | ☒ | ☐ |
| 15. Cessation of operations | ☒ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| — Construction | ☒ | ☐ | ☐ | ☐ |
| — Drainage controls | ☒ | ☐ | ☐ | ☐ |
| — Surfacing | ☒ | ☐ | ☐ | ☐ |
| — Maintenance | ☒ | ☐ | ☐ | ☒ |
| 17. Other transportation facilities | ☒ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☒ | ☐ | ☐ | ☐ |

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 3/13/91

Please number comments to correspond with topics on previous page.

RECORDS

- Permit for 5 year period approved by the Division on 8/7/89.
- Last permit amendment was approved on 11/1/90 effective 10/29/90.
- No outstanding stipulations exist. Last stipulation 817.23(1)(HS) approved 9/6/89.
- UPDES permit of record and dated 5/1/89.
- Surety bond, policy # U-629894 of record for $2,441,745.00
- Reclamation agreement on file, but does not have signature of the Division Director
- Liability insurance of record, dated 1-1-88 and good for the life of the loadout/permit
- SPCC plan on file and dated March, 1990.
- No blasting records were on file, because no surface blasting has taken place.
- Water monitoring records were submitted to the Division on 1/23/91 - 4th Q, 90.
- UPDES discharge report for the 4th Q. 1990 dated 1/24/91 was submitted to Division
- Vegetation monitoring was completed and dated Feb. 1990.
- Refuse pile certified report dated 12/20/90
- Annual 1990 pond certified report on six ponds was of record & dated 12/20/90.
- The road certification was of record and dated 4/20/90.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 3/13/91

Please number comments to correspond with topics on previous page.

Field Observations

· Followup on previous reportable items:

△ Culvert C-5 adjacent to coal silo and on a ditch that drains pond 5 (fine) has recently been cleaned but needs additional maintenance now that the temperatures have moderated and prolonged ice buildup is no longer a problem. This also applies to Culvert C-6

△ Basins discussed in Munson inspection report of 1/17/91 have not been constructed nor has an amendment been submitted as requested. Mr. Guy stated now that weather conditions for on the ground work has improved he will discuss this matter with Munson.

△ The berm dividing disturbed from undisturbed

△ Additional outlet protection in the form of riprap was installed as requested in the partial inspection report dated 2/21/91.

· Ponds 5 & 6 contained water and were not discharging. All ponds were stable.

· Siltfences were in good shape and no problems.

· BTCA areas were observed and no problems noted.

· Roads were watered and no fugitive road dust was observed

Copy of report mailed to BCCC/Don Guy; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tim J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE