0015

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

pgl

inspection report

Permit No. ACT/007/022
Inspection Date 2/21/91

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine C.V. Spur ☐ Surface ☐ Underground ☒ Other
County Carbon State Ut.
Company Official(s) Clay Cloward.
State Official(s) Bill Malencik
Time of inspection 10:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 1/17/91 Weather conditions Clear/Cool
Acreage 160 ☒ Permitted 108 ☐ Disturbed ☐ Regraded ☐ Seeded 108 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐
19. Other Prep Plant.	☒			☒

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 2/21/91

Please number comments to correspond with topics on previous page.

General Comments. Most of the maintenance work identified in the inspection report of 1/17/91 (Munson) had been completed. Some work still remains and this will be done at the next inspection to determine if all has been completed.

Diversions. Culvert outlet east of the topsoil pile ~~north~~ north of the road adjacent to the refuse pile needs to have additional protection. The ditch that drains water from the water filling area needs to be maintained.

Sediment Ponds. The two lower sediment ponds contained water, were stable, and were not discharging. All the other ponds were dry and no problems noted.

Refuse Pile. The refuse pile had recently been graded and compacted. The slopes were stable and no erosion was observed.

Roads. The roads were in good shape and were water to control fugitive dust.

Copy of report mailed to BCCC/Dan Guy; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Tom J. Malmrick No. 26.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

3/5/91