0016

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

OSM Oversight Inspection

inspection report

Permit No. ACT/007/022

Inspection Date 1/17/91

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. BOX 1378

City Price State Utah Zip 84501

Mine C.J. SPUR (LOADOUT) ☐ Surface ☒ Underground ☐ Other

County CARBON State UT

Company Official(s) DAN GUY

State Official(s) TOM MUNSON and JEFF ZINGO (OSM)

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 4:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 12/13/90 Weather conditions SUNNY

Acreage 160 ☐ Permitted 108 ☐ Disturbed ☐ Regraded ☐ Seeded 108 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	✓			✓
2. Signs and markers	✓			
3. Topsoil	✓			✓
4. Hydrologic balance				
— Stream channel diversions				
— Diversions	✓			✓
— Sediment ponds and impoundments	✓			✓
— Other sediment control measures	✓			
— Surface and groundwater monitoring	✓			
— Effluent limitations	✓			
5. Explosives			✓	
6. Development waste and spoil disposal			✓	
7. Coal processing waste	✓			✓
8. Noncoal waste	✓			
9. Protection of fish, wildlife, and related environmental values	✓			
10. Slides and other damage	✓			
11. Contemporaneous reclamation	✓			
12. Backfilling and grading	✓			
13. Revegetation	✓			
14. Subsidence control	✓			
15. Cessation of operations	✓			
16. Roads				
— Construction	✓			
— Drainage controls	✓			
— Surfacing	✓			
— Maintenance	✓			
17. Other transportation facilities	✓			
18. Support facilities and utility installations	✓			

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 1/17/91

Please number comments to correspond with topics on previous page.

3. TOPSOIL - It was observed that several areas within the disturbed area are vegitated and undisturbed. The issue that topsoil from these areas must be protected was discussed with the operator and it was decided that this policy be reinforced to all working personnel and signs be used to warn workers of potential topsoil impact areas.

4 b Diversions - Culverts C-5 and C-6 appeared to have a build up of sediments upstream and downstream of their inlets and outlets. The capacity of culvert C-5 is greater than the required 1.35' of head needed to pass the design flow and therefore is in compliance with the approved plan. It was discussed that when frozen conditions and weather

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 1/17/91

Please number comments to correspond with topics on previous page.

dictate that the operator clean the ditch below culvert C-5 and restore its original capacity as well as implement ~~to~~ accessible clean-out basins prior to culverts C-5 and C-6. The operator was requested to submit an amendment prior to implementing the work, as it was felt this would be a permit amendment. It was argued this would allow the culverts to remain free of sediments and help improve overall maintanence of the diversions.

The berm separating the disturbed and undisturbed diversion on CD-1 adjacent to pond 6 will be maintained to prevent potential commingling of disturbed and undisturbed water. None had occurred but maintanence was recommended in one small area.

Impoundments - No problems were noted

Copy of report mailed to PAT 604/BCCC; John Hatten/OSM

Copy of report given to JOE HELFRICH

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE