9-24-87

0009

File

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/033

Inspection Date 9/17/87

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price, Utah State Ut. Zip 84501

Mine Wildcat Prep. Plant ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) John Pappas, Joe Baker (Phone Contact Mike Glasson)

State Official(s) Wm. J Malencik, Harold Sandbeck

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection August 31, 1987 Weather conditions Clear/pleasant

Acreage — ☐ Permitted 47 ☒ Disturbed — ☐ Regraded — ☐ Seeded — ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 9/17/87

Please number comments to correspond with topics on previous page.

Followup To Previous Inspections: Half-round culvert inlet protection has been installed on sediment ponds C, D, & E. New signs have been installed at the three road ingress/egress areas.

Permit. The company is currently operating under an interim authorization. They plan to submit a formal application on or before 12/31/87

The required paperwork in connection with a complete inspection was reviewed & found to be in order.

Sediment Pond. Some additional compliance work was identified on sediment pond inlets as related to protection. The work was completed before we departed the site.

None of the sediment ponds had water & records revealed stable conditions per weekly pond inspection reports and validated by the instant inspection.

Diversions: Maintenance and erosion protection is required on the dith that runs in a northerly direction about 200'. This is the drainage ditch on the north side of the exit haul road. It is suggested that Mike Glasson

Copy of report mailed to MIKE GLASSON, PRI; Brian Smith OSM

Copy of report given to Joe Helfrich

Inspector's signature Tim J. Thalenick No. 26

9/17/87

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

Mailed to operator 9/18/87 TMM

DOGM/IR-2 an equal opportunity employer 11/86 001049

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 9/17/87

Please number comments to correspond with topics on previous page.

contact John Whitehead and make a ditch design proposal that will be acceptable as part of the permit approval. This was discussed by phone with Mike Glasson.

Road Drainage/Culverts. Several culvert maintenance items were identified and discussed. While these items are still in compliance, yet they are something that needs to be observed repeatedly in the immediate future. However, John Pappas said he would put a crew on such work before it becomes a potential problem. As we were leaving the mine site a crew had started to work on the culverts.

Other. An undisturbed drainage on the S.W quadrant drains through a 36" culvert and enters a natural undisturbed gulley. By pacing the distance between the gulley & culvert is about 150'. The culvert was installed under the railroad before 1977 and the railroad serviced old mines that were operational in and around 1930. Concrete drop apron has been installed in the gulley. By copy of this report I am requesting Mike Glasson to field check this matter and call me by Sept. 28, 1987. The concern is the stability of the gulley.

Copy of report mailed to MIKE GLASSON, ARI; BRIAN SMITH OSM

Copy of report given to Joe Helfrich

Inspector's signature Wm. J. Malinick No. 26

9/17/87

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE