0019

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/033

Inspection Date 6/17/88

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut. Zip 84501

Mine Wildcat Prep Plant ☐ Surface ☐ Underground ☒ Other

County Carbon State UT

Company Official(s) John Pappas

State Official(s) Jim Fricke, Bill Warnack

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☐ p.m. ☐ Partial ☒ Complete

Date of last inspection 5/6/88 Weather conditions Warm

Acreage ☐ Permitted (60 ☒ Disturbed) ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☒	☐	☐	☒
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☒	☐	☐	☐
e. Surface and groundwater monitoring	☒	☐	☐	☐
f. Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
a. Construction	☒	☐	☐	☐
b. Drainage controls	☒	☐	☐	☐
c. Surfacing	☒	☐	☐	☐
d. Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PR0/007/033

Inspection Date 6/17/88

Please number comments to correspond with topics on previous page.

4a. UD-1 (undisturbed diversion) on Plate II of the recently submitted PAP does not coincide with the field disposition. Although the site is not permitted, Plate II should be modified to reflect the actual disposition of Plate II or the diversion should be constructed to the specifications of Plate II.

b. All disturbed area diversions were functional at the time of inspection. Ditch D-1 (Plate II) has been lined with conveyor belting. The outfall of the culverts in D-1 will require additional erosion protection. The operator has placed riprap at the outfall and intends to secure the riprap with concrete.

c. The A portion (approx. 6.0 feet) of Pond E inlet will require additional riprap. The operator has recently cleaned Pond E; ~~and due to the~~ the new shape of the Pond floor will require additional inlet riprap ~~to [redacted]~~

13. ~~All~~ The area between Ponds A and B has been revegetated and appears to maintain good growth.

16d. The roads were in good condition, the operator had applied magnesium chloride to roads and fugitive dust has been abated.

Copy of report mailed to Brian Smith (OSM), Joe Helfrich (DOGM), PFO, Andalex Resources, Inc. Mike Glasson

Copy of report given to Joe Helfrich

Inspector's signature Jim Trickle No. 22

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE