7160 0001

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Job pgl

inspection report

Permit No. ACT/007/033

Inspection Date 12/27/90

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State UT Zip 84501

Mine Wildcat Loadout ☐ Surface ■ Underground ☒ Other

County Carbon State UT

Company Official(s) John Pappas

State Official(s) S. White

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 11:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/29/90 Weather conditions Fair and Cold

Acreage 100 ☐ Permitted 60 ☐ Disturbed ☐ Regraded ☐ Seeded 60 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☑	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☑	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☑	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 12/27/90

Please number comments to correspond with topics on previous page.

3. The topsoil piles were seeded. Topsoil Pile #2 & #3 were completely seeded. At the time of inspection they were being fertilized. Topsoil Pile #1 was seeded on the sides only, some vegetation was on the top. No mulch had been applied. John Pappas was notified that a violation will be issued if mulch is not applied by the next inspection.

4. The new impoundment on the west side of the property has not been started. Mr. Pappas indicated that plans had just been recived and construction would start soon.

Sediment ponds were all dry, snow was on the ground. Sediment Pond F has a colony of cottontail rabbits living underneath the chalf round inlets.

At the time of inspection the operator was spreading coal to reduce the temperature and fires.

Copy of report mailed to Mike Glasson/Andalex; John Kathman/OSM

Copy of report given to Joe Helfrich

Inspector's signature Susan White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer