0007

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

JA page

inspection report

Permit No. ACT/007/033
Inspection Date 8/14/91

Permittee/Operator Name Andalex Resources, Inc
Business Address P.O. Box 902
City Price State Ut Zip 84501
Mine Wildcat Hollow ☐ Surface ☐ Underground ☒ Other
County Carbon State Ut
Company Official(s) John Pappas
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 7/11/91 Weather conditions Clear/Warm
Acreage 100 ☐ Permitted 60 ☐ Disturbed ☐ Regraded ☐ Seeded 60 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 8/14/91

Please number comments to correspond with topics on previous page.

Sediment Ponds & Impoundments. The construction of the impoundment has been completed. The impoundment has two spillways (culvert) with outlet protection.

Sediment ponds A-F were dry and no problems noted. Sediment pond B had been cleaned. The sediment marker had not been reinstalled. However, the operator they had to survey the pond before the marker could be reinstalled.

Coal Waste. The bony/refuse pile was checked. The bony was stored in small piles. It appears that very little bony is currently being processed. Therefore, it may be a month or more before sufficient material is stored to make the next lift

Roads. Roads were in good shape including the drain ditches.

The small piping holes mentioned in the oversight inspection of 5/14/91 have been repaired. A culvert/downspout has been installed on one area. The permittee stated he has one more downspout to install which will eliminate any further potential problems.

Copy of report mailed to ADI/Mike Glasson; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

8/15/91