0002

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. EXP/007/038 Inspection Date: October 7, 1992
Permittee and/or Operators Name: Cypress Western Coal Company
Business Address: P.O.Drawer PMC City: Price State: UT Zip: 84501
Mine Name: Blackhawk Site County: Carbon State: Utah
Type of Mining Activity: Underground ____ Surface ____ Other XX
Company Officials: Steve Rigby State Officials: Steve Demczak
Time of Inspection: 9:00 a.m. - 2:00 p.m. Partial ____ Complete: X
Acreage: Permitted ____ Disturbed ____ Regraded ____
Seeded 0 Bonded 0 Date of Last Inspection: September 10, 1992
Weather Conditions: Cool 60's Enforcement Action: None

CATEGORIES

		YES	NO	N/A	NOTES
1.	PERMITS	X			
2.	SIGNS AND MARKERS	X			
3.	TOPSOIL	X			X
4.	HYDROLOGIC BALANCE:				
	a. STREAM CHANNEL DIVERSIONS	X			
	b. DIVERSIONS	X			X
	c. SEDIMENT PONDS AND IMPOUNDMENTS	X			
	d. OTHER SEDIMENT CONTROL MEASURES	X			
	e. SURFACE AND GROUNDWATER MONITORING			X	
	f. EFFLUENT LIMITATIONS	X			
5.	EXPLOSIVES	X			
6.	DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	X			X
7.	COAL PROCESSING WASTE			X	
8.	NONCOAL WASTE	X			
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	X			
10.	SLIDES AND OTHER DAMAGE			X	
11.	CONTEMPORANEOUS RECLAMATION	X			
12.	BACKFILLING AND GRADING	X			
13.	REVEGETATION	X			
14.	SUBSIDENCE CONTROL	X			
15.	CESSATION OF OPERATIONS	X			
16.	ROADS				
	a. CONSTRUCTION	X			
	b. DRAINAGE CONTROLS	X			
	c. SURFACING	X			
	d. MAINTENANCE	X			
17.	OTHER TRANSPORTATION FACILITIES	X			
18.	SUPPORT FACILITIES UTILITY INSTALLATIONS	X			
19.	AVS Check	X			

Permit No. EXP/007/038 Inspection Date October 7, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

4b. Diversions -

The diversions were inspected for performance standards and no problems were noted at the time of inspection. Maintenance had occurred to the diversion at the fan site since last inspection.

3. Topsoil -

Topsoil has been stored throughout the property and is surrounded by berms. The topsoil does contain some refuse do to the fact that this was a past mine site.

7. Coal Processing Waste -

There is a possibility that there will be a stockpile of refuse from under ground in order to have the ability to explore. The majority will come from sluffage from coal seam to existing roads.

Copy of report:

Mailed to: Plateau Mining Company
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO
Date: November 4, 1992

Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak