0011 RY 1-87

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

File

inspection report

Permit No. INA/015/002
Inspection Date 4/21/87

Permittee/Operator Name Western States Minerals
Business Address 4975 Von Bordon Street, Wheatridge Co 80033
City Wheatridge State Colorado Zip 80033
Mine J.B. King ☐ Surface ☑ Underground ☐ Other
County Emery State Utah
Company Official(s) None
State Official(s) Tom Munson
Time of inspection 12:00 ☐ a.m. ☑ p.m. to 2:00 ☐ a.m. ☑ p.m. ☐ Partial ☑ Complete
Date of last inspection 1/29/87 Weather conditions Sunny
Acreage 480 ☑ Permitted 28.2 ☑ Disturbed 28.2 ☑ Regraded 28.2 ☑ Seeded 28.2 ☑ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☒
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☐	☐	☒	☐
— Drainage controls	☐	☐	☒	☐
— Surfacing	☐	☐	☒	☐
— Maintenance	☐	☐	☒	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 4/21/87

Please number comments to correspond with topics on previous page.

1) Permits: All permit documents and related correspondence for this site are on file at the operator's Wheatridge Colorado Office and at the Division's Office in Salt Lake City, Utah. All pertinent information was reviewed at the Salt Lake Office.

4a) The Division received a revised work plan for the repair and maintenance of the erosion which has occurred at the J. B. King site on March 11, 1987. The Division concurs with this plan and the actual work is to be carried out in third week of May. A division representative will be on site to help oversee the g&f and make sure the appropriate repair items are carried out. Western States Minerals Charles S. Williams has assured the division that all our items of concerns spelled out in our December 17, 1986 letter will be

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 4/21/87

Please number comments to correspond with topics on previous page.

taken care of. He is personally lining up contractors and ordering gravel and riprap for reconstruction of the feeder ditch and main channel.

4c. All runoff from the site has been routed to the sediment pond. The pond is drying up and is less than 10 % of total capacity. No evidence of discharge has occurred.

General Comment:

As well as could be determined, cattle had been inside the fenced area (tracks, etc.) and some of the revegetation, particularly the fourwing saltbush, has been grazed. In conversations with Charles Williams of Western States Minerals he assured the division the problem will be taken care of. He is determining who has the allotment and will talk with

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

the rancher to prevent any further damage. If this can not be accomplished he will install the heavy duty gate as mentioned in this last inspection report. The gate was up when [redacted] arrived at the site and the pond had much less water in it than the last inspection (maybe the incentive for the rancher to let his cattle in the property as well as the grazing of the revegetation).

Copy of report mailed to John Hathmann, Charles Williams

Copy of report given to Joe Helfrich

Inspector's signature Thomas Munson 6/1/87 No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer