0010

A

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

gch

INSPECTION REPORT

INSPECTION DATE & TIME: July 6, 1988
10-11 a.m.

Permittee and/or Operators Name: Western States Minerals Corporation
Business Address: 4975 Van Gordon Street Wheat Ridge, Colo. 80033
Mine Name: J.B. King Permit Number: ~~ACT/015/002~~
Type of Mining Activity: Underground XX Surface ____ Other ____
County: Emery State: Utah
Company Official(s): None
State Official(s): Bill Warmack and Tom Munson
Partial: XX Complete: ____ Date of Last Inspection: June 21, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 480 Disturbed 30 Regraded 30 Seeded 30 Bonded 30
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	(X)
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	(X)	( )
7. COAL PROCESSING WASTE	( )	( )	(X)	( )
8. NONCOAL WASTE	( )	( )	(X)	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	(X)	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(X)	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	(X)	( )	( )	(X)
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	(X)	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	(X)	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	(X)	( )
d. MAINTENANCE	( )	( )	(X)	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(X)	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	(X)	( )

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: ACT/015/002 DATE OF INSPECTION July 6, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Ground conditions were moist; visual evidence of previous precipitation was present.

4b. DIVERSIONS:

Stream channel has been repaired; however, apron below #2 check dam (from top) in feeder ditch is washing out a little. Also, some minor erosion was noted at the top of the ditch. Additional rock work may be required at these two locations to prevent any future damage.

4d. OTHER SEDIMENT CONTROL MEASURES:

1. All silt fences along fill slope were up and functioning properly. Fences may have to be extended or add berms along outer edges to prevent additional water flows around ends.

2. Top silt fence/check dam in main channel needs some bank repair; may have to extend and rekey further into bank.

3. Number 2 silt fence/check dam has been blown out; it should be removed.

13. REVEGETATION:

1. The bare areas where equipment was operating need to be reseeded this fall per the Division's recommendations.

2. Fence along southern ridge needs to be completed before fall to eliminate access by cattle. This area was previously discussed with Larry Johnson of Western States. Also, main entrance gate needs repair.

Copy of this Report:
Mailed to: Larry Johnson, Western States Minerals
Mailed to SLC for: Brian Smith, OSM; Joe Helfrich and Tom Munson, DOGM
Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: July 13, 1988