0002

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jah pgl

inspection report

Permit No. INA/015/002
Inspection Date December 7, 1990

Permittee/Operator Name Western States Minerals Corporation
Business Address 4975 Van Gordon Street
City Wheat Ridge State Colorado Zip 80033
Mine J.B. King ☐ Surface ☒ Underground ☐ Other
County Emery State Utah
Company Official(s)
State Official(s) Jess Kelley
Time of inspection 1 : 30 ☐ a.m. ☒ p.m. to 4 : 30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection November 27, 1990 Weather conditions Cold and sunny
Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date December 7, 1990

Please number comments to correspond with topics on previous page.

SIGNS & MARKERS

The disturbed area boundaries are in the process of being updated (see submittal dated November 12, 1990 from Frank Filas of Western States to the Division). Disturbed area markers and proposed boundaries are well-marked and well-placed and are adequate.

SUBSIDENCE CONTROL

The area to the south of the mine site, where subsidence cracks have recently been repaired, looks good. No other cracks have appeared and the vegetation disturbed and destroyed in the repair process is reestablishing itself.

Copy of report mailed to Frank Filas/Western States; Brian Smith/OSM

Copy of report given to Joe Helfrich/DOGM

Inspector's signature Jim W. Kelley No. 34

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer